


Repair of DC converter generator BV25 and BGC1



Use: The high-energy units are a components of X-ray units

Error-description: Because of dissolution of potting it comes to electric flashovers and the destruction of components.

Error correction: The old potting compound is removed completely. For the determination of defective parts is carried out under strongly lowered high voltage is a function check. After repair, the product is poured and conducted a new audit function under operating conditions.